

## Message Text

UNCLASSIFIED

PAGE 01 MANILA 13002 200403Z

63

ACTION FBO-01

INFO OCT-01 EA-07 ISO-00 /009 W  
----- 035608

R 200325Z NOV 73  
FM AMEMBASSY MANILA  
TO SECSTATE WASHDC 9276

UNCLAS MANILA 13002

FOR FBO

E.O. 11652: N/A  
TAGS: ABLD, RP  
SUBJECT: TYPHOON DAMAGE - EMERGENCY REPAIRS

EMERGENCY REPLACEMENT OF ALL PRIMARY HIGH-VOLTAGE UNDERGROUND  
CABLES WAS COMPLETED OCTOBER 31. TOTAL BILLING FROM SUBIC IS  
DOLLARS 5,322.75; CONSISTING OF DOLLARS 4,790.55 FOR MATERIALS  
AND DOLLARS 532.20 FOR LABOR. TOTAL BILLING FROM MANILA ELECTRIC  
COMPANY IS DOLLARS 1,612.43 CONSISTING OF DOLLARS 1,009.76  
FOR LABOR AND DOLLARS 602.67 FOR MATERIALS. OM WITH SCHEMATIC  
DIAGRAM TO FOLLOW GIVING DETAILS. REQUEST POST M&R ALLOTMENT BE  
INCREASED DOLLARS 6,935.18 TO PAY FOR EMERGENCY REPLACEMENT OF  
CABLES.  
SULLIVAN

UNCLASSIFIED

NNN

## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01 JAN 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** n/a  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 20 NOV 1973  
**Decaption Date:** 01 JAN 1960  
**Decaption Note:**  
**Disposition Action:** n/a  
**Disposition Approved on Date:**  
**Disposition Authority:** n/a  
**Disposition Case Number:** n/a  
**Disposition Comment:**  
**Disposition Date:** 01 JAN 1960  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1973MANILA13002  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** n/a  
**Enclosure:** n/a  
**Executive Order:** N/A  
**Errors:** N/A  
**Film Number:** n/a  
**From:** MANILA  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1973/newtext/t19731123/aaaaaqnv.tel  
**Line Count:** 40  
**Locator:** TEXT ON-LINE  
**Office:** ACTION FBO  
**Original Classification:** UNCLASSIFIED  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 1  
**Previous Channel Indicators:**  
**Previous Classification:** n/a  
**Previous Handling Restrictions:** n/a  
**Reference:** n/a  
**Review Action:** RELEASED, APPROVED  
**Review Authority:** golinofr  
**Review Comment:** n/a  
**Review Content Flags:**  
**Review Date:** 06 DEC 2001  
**Review Event:**  
**Review Exemptions:** n/a  
**Review History:** RELEASED <06-Dec-2001 by cunninfx>; APPROVED <18 MAR 2002 by golinofr>  
**Review Markings:**

Declassified/Released  
US Department of State  
EO Systematic Review  
30 JUN 2005

**Review Media Identifier:**  
**Review Referrals:** n/a  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**Secure:** OPEN  
**Status:** NATIVE  
**Subject:** TYPHOON DAMAGE - EMERGENCY REPAIRS EMERGENCY REPLACEMENT OF ALL PRIMARY HIGH-VOLTAGE UNDERGROUND  
**TAGS:** ABLD, RP  
**To:** STATE  
**Type:** TE  
**Markings:** Declassified/Released US Department of State EO Systematic Review 30 JUN 2005